

20030303* 6420600

FIG. 1




FIG. 3

301 Customer ID	302 Name	303 Postal Code	304 Address	305 Phone Number	306 Floor Plan
00078723	Katsue Isono	123 -4567	Kadomatsu-cho 1-1, Kadomatsu-shi	06(6378) 5678	00078723m1 00078723m2
00078724	Makio Isobe	234 -0056	Moriguchi-cho 2-22, Morita-shi	078(81) 1234	00078724m1


APPROVED	CC	10
BY	CLASS	SUB
DRAFTSMAN		

209030 640600T

FIG. 4


201		301		203		204		401	
Appliance ID		Customer ID		Manufacturer Code		Model Code		Connection Point	
000001		00078723		0034		PQ01-83		1K01	
000002		03990212		0034		TV03-05		1L16	
000003		00078723		0034		PQ01-83		2L05	

FIG. 5




20090709 10:06:00

FIG. 6



10000779-03000

FIG. 7




20090329 62205007

2023-06-06

FIG. 8


Operation Mode	Temperature Difference ΔT	Preset Temperature Reaching Time Δt	Compressor Rotational Frequency
Cooling	2.3	6.0	2000
Cooling	5.0	10.7	2210
Cooling	3.2	6.8	2033
Cooling	3.3	6.9	2008
Heating	3.5	3.7	2039
Heating	5.5	5.0	2157
Heating	3.0	3.5	2001
Heating	2.0	3.0	1899
Heating	2.2	3.0	1948
Heating	3.6	3.7	2030
Heating	4.8	4.5	2074
Heating	2.5	2.9	1975

FIG. 9



1009079-030602

FIG. 10



10090779-030602

FIG. 11A




FIG. 11B

1201	Failure Information	Customer: Katsue Isono
1202	Address:	Kadomatsu-cho1-1, Kadomatsu-shi
1203	Phone Number:	06-6378-5678
1204	Location:	1F Kitchen(1K01)
1205	Manufacturer Code:	034
1206	Mode Code:	PQ01-83
1207	Appliance ID:	000001
1208	Abnormal Component:	Compressor
1209	Abnormal Code:	PQX-822
1210	Part Code:	PQP-07, PQS-15
1211	Sketch:	1F, Ms. Isono's House